13864

13864

Survey for: JIM JOHNSON

Description: Lot 4, Block 5, LA BUENA VISTA

I hereby certify that this is a true and correct representation of a survey of the boundaries of the land above described and of the location of all buildings, if any, thereon, and all visible encroachments, if any, thereon.

Dated this 5th day of August, 1965.

50%

Scale: 1" - 16'

WILLIAM A. CARLSON SURVEYOR
2324 West 110th Street

by _____
Minn. Reg. No. 5048



13864

5512 McGuire Rd
05-116-21-43-0012